

Document Separator Sheet



Document Title:

RECEIPT OF ACTIONS TAKEN OR PLANNED ON RECOMMENDATIONS FROM RADIOLOGICAL AFFAIRS
SUPPORT OFFICE VISIT ON 19 JULY '978

Document ID/File Name:

3593



Document Date:

10/24/1978

In NRIS:

NO

Installation:

AGANA_NAS

Author Affiliation:

E.D. ESTES

Contract Number/CTO:

Command:

MARIANAS

Notes:

Original Box #:

80

MSI Scan Box #:

69





U. S. NAVAL AIR STATION
FPO SAN FRANCISCO 96637

IN REPLY REFER TO:

40400:TJM:igb

4790

SER 1361

24 OCT 1978

From: Commanding Officer, U. S. Naval Air Station, Agana, Guam
To: Officer-in-Charge, Naval Nuclear Power Unit, Port Hueneme,
California 93043

Subj: Radiological Affairs Support Office Technical Assistance
Visit of 19 July 1978; response to

Ref: (a) Officer-in-Charge, Naval Nuclear Power Unit, Port Hueneme,
CA ltr SER 994 of 15 Aug 78
(b) RASO Report No. 117A of 15 Aug 78
(c) OPNAVINST 4790.2A

1. In response to reference (a), the following information is provided as recommended by reference (b):

a. In accordance with reference (c), the Aircraft Intermediate Maintenance Officer has the overall responsibility for radiation safety within the Department. However, in the interest of exercising independent judgment in developing and administering the radiation safety program, a Maintenance Instruction now designates the Aircraft Intermediate Maintenance Department, Airframes Division Officer as the Radiation Safety Officer.

b. AIMD Quality Assurance Division has ensured that DD1141 Form is filed in individual health records. Periodic reviews of health records will be conducted through quarterly audits by Quality Assurance.

c. A daily pocket dosimeter log has been initiated and is being maintained in accordance with NA 01-1A-16.

d. Two ionization-type survey instruments have been obtained, calibrated, and are presently in use.

e. All pocket dosimeters have been calibrated and included in a cyclical calibration system.

f. A utilization log has been initiated and is being maintained for all radiographic exposures.

g. A maintenance instruction consisting of radiological safety procedures and radiographers' responsibilities is being written.

E. D. ESTES
E. D. ESTES

Copy to:

NAVFACENGCOM (04N)

NAVAIRSYSCOM (5324K)

~~NAVAIRSYSCOM (992A)~~