



DEPARTMENT OF THE AIR FORCE
36TH MEDICAL OPERATION SQUADRON (PACAF)
Unit 14010 (Andersen AFB, Guam)
APO AP 96543-4010

23 October 2015

MEMORANDUM FOR 554 RHS/CC

FROM: 36 MDOS/SGOAB

SUBJECT: Radioactive Material (RAM) Permit #GU-00300-01/01AFP Audit/Review

References: (a) AFI 40-201, *Managing Radioactive Materials in the US Air Force*
(b) *Soil Density Gauge Compliance Checklist for Permit Radiation Safety Officer*, AFIA/SG, 2013
(c) NUREG 1556, Vol 1, Rev 2, Appendix E


1. On 19 Oct 2015, Capt Lathbury and SSgt Clay from Bioenvironmental Engineering (BE) audited your unit's Radiation Safety Program for RAM Permit in subject. The listed references above were used as guidance. The Permit and related radiation safety program are in compliance.

2. Preliminary findings were provided to your Unit RSO on the same day. BE discussed the items listed in the table below.

Program Requirement	Note
Permit & Program Documentation	Full compliance
Permit Radiation Safety Officers	Full compliance
Authorized Gauge Users	Permit needs to be updated to reflect new personnel in the shop.
Gauge Radiation Protection Program	Full compliance
Hazard Posting & Signage	Full compliance
Gauge Maintenance	Full compliance
Gauge Leak Tests	Full compliance
Public Dose Compliance	Full compliance
Occupational Dose Compliance	Full compliance
Occupational Dose Monitoring (Dosimetry)	N/A
Receipt of Gauge	Full compliance
Gauge Transfers	N/A
Permitted Materials Shipment & Transport	N/A
Radiation Survey Instrumentation & Method	Full compliance
Emergency Response Plan	Full compliance
Accident or Incident Reporting	Full compliance
Prior Deficiencies	Full compliance

3. This permit was last inspected by Nuclear Regulatory Committee on June 23, 2015. At that time the permit was found to be "Compliant" and no further actions were required. The Air Force Inspection Agency (AFIA) last inspected this permit on February 19, 2014. The AFIA inspection period for this permit is every two years, so it is due for inspection in 2016. Although the AFIA inspection frequency for this permit is every two years, the RAM permit and radiation safety program is liable to be inspected without notice from the Nuclear Regulatory Commission.

4. If you have any questions please contact us at 366-7166.




GREGORY J. LATHBURY, Capt, USAF, BSC
Alternate Installation Radiation Safety Officer

1st Ind, 554 RHS/CC

MEMORANDUM FOR 36 MDOS/SGOAB

Receipt acknowledged on 4 Nov 15



ANDREW E. DEROSA, Lt Col, USAF
Commander, 554th RED HORSE Squadron